Figure 1: Aircraft submerged in river

Figure 2: Aerial view of the airplane submerged in river

Figure 3: Left main landing gear sticking out of the water

Figure 4: Aircraft partially submerged in river

Figure 5: Side view of aircraft partially submerged in river



Figure 6: ADS-B flight track

Figure 7: Right side exhaust stack

Figure 8: Right side exhaust muffler and heat shroud

Figure 9: Right side exhaust muffler top view

Figure 10: Bottom view of engine on stand